

This manifest
was replaced
by mfst. #
01675/92301675

92301612
CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7531

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address Douglas Aircraft Company 19503 S. Normandie Avenue Torrance, CA 90502		4. Generator's Phone (310) 533-7926 OR (310) 533-7231	Attn: R. Tuell Mail Code: C6-59	A. State Manifest Document Number 92301672	
5. Transporter 1 Company Name Laidlaw Environmental Services of CA, Inc.		6. US EPA ID Number CA D000083121		B. State Generator's ID H A H Q 36005698	
7. Transporter 2 Company Name Disposal Control Service		8. US EPA ID Number CA T080034184		C. State Transporter's ID H A H Q 36005698	
9. Designated Facility Name and Site Address Norris Environmental Services 5215 S. Boyle Avenue Los Angeles, CA 90058		10. US EPA ID Number CA D0197030993		D. Transporter's Phone (310) 518-4700	
				E. State Transporter's ID 412148	
				F. Transporter's Phone 909-983-0392	
				G. State Facility's ID	
				H. Facility's Phone (213) 588-7111	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number State EPA/Other
a. RQ, Waste Corrosive Liquids, N.O.S. (Chromic acid, Nitric Acid), 8, UN1760, PG II, (D002, D007)		0101 TT	07580	P	State 792 EPA/Other D002
b.					State EPA/Other
c.					State EPA/Other
d.					State EPA/Other
J. Additional Descriptions for Materials Listed Above a) ID# E0106200002 CR: Chromic Acid Anodizing Solution From Baker Tank Area with Rinse water from Tank 95 Titanium Pickle Tank. Chromic acid 4-6%, Nitric acid 0-1%, Hydrofluoric acid 0-1%, Active 0-0.1%, Water 92-100%		K. Handling Codes for Wastes Listed Above b. c. d.			
15. Special Handling Instructions and Additional Information Emergency Response Telephone Number (800) 424-9300 (Chemtrec) DOT ERG # 60 Ia. Additional EPA Waste Code D007. EH Permit # 4-93052513					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month Day Year 12/1/93	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name James Auel		Signature James Auel		Month Day Year 12/1/93	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Signature Month Day Year					

DO NOT WRITE BELOW THIS LINE.

92301612

GENERATOR

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7515

TRANSPORTER
FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address Douglas Aircraft Company 19503 S. Normandie Avenue Torrance, CA 90502		4. Generator's Phone (310) 533-7926 or (310) 533-7231	5. Transporter 1 Company Name Laidlaw Environmental Services of CA, Inc.	6. US EPA ID Number CA D000083121	7. Transporter 2 Company Name Disposal Control Service
8. US EPA ID Number CA T080034184		9. Designated Facility Name and Site Address Norris Environmental Services 5215 S. Boyle Avenue Los Angeles, CA 90058		10. US EPA ID Number CA D097030993	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. RQ, Waste Corrosive Liquids, N.O.S. (Chromic acid, Nitric Acid), 8, UN1760, PG II, (D002, D007)		001	TT	07580	P
b.					
c.					
d.					
J. Additional Descriptions for Materials Listed Above QID# E0106200002 CR: Chromic Acid Anodizing Solution From Baker Tank Alkal with Rinse water from Tank 35 Titanium Pickle Tanks Chromic acid 4-6%, Nitric acid 0-1%, Hydrofluoric acid 0-1%, Active 0-0.1%, Water 92-100%		K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Response Telephone Number (800) 424-9300 (Chemtree) DOT ERG #60 1a. Additional EPA Waste Code D007. EH Permit # 4-93052513					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month Day Year 12/1/93	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name James Axel		Signature James Axel		Month Day Year 12/1/93	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name		Signature		Month Day Year	

DO NOT WRITE BELOW THIS LINE.

See Instructions on back of page 6.

Department of Toxic Substances Control
Sacramento, California

923016/2

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7555

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address Douglas Aircraft Company Attn: R. Tuell 19503 S. Normandie Avenue Mailcode: C6-59 Torrance, CA 90502 4. Generator's Phone (310) 533-7926 or (310) 533-7231		5. Transporter 1 Company Name Laidlaw Environmental Services of CA, Inc. 7. Transporter 2 Company Name Disposal Control Service 9. Designated Facility Name and Site Address Norris Environmental Services 5215 S. Boyle Avenue Los Angeles, CA 90058		6. US EPA ID Number CAID1010100831121 8. US EPA ID Number CA17080034184 10. US EPA ID Number CAID097030993		A. State Manifest Document Number 92301672 B. State Generator's ID HIAHQ3610951981 C. State Transporter's ID 4112148 D. Transporter's Phone (310) 518-4700 E. State Transporter's ID 412148 F. Transporter's Phone (310) 983-0342 G. State Facility's ID H. Facility's Phone (213) 588-7111	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type		13. Total Quantity	14. Unit Wt/Vol	1. Waste Number State EPA/Other	
a. RQ, Waste Corrosive Liquids, N.O.S. (Chromic acid, Nitric Acid), 8, UN1760, PG II, (D002, D007)		0101 TIT		075810	P	792 D002	
b.						State EPA/Other	
c.						State EPA/Other	
d.						State EPA/Other	
J. Additional Descriptions for Materials Listed Above QID# E0106200002 CR: Chromic Acid Acidizing Solution From Baker Tank Mixed With Rose water from Tank 55 Titanium Pickle Tanks Chromic acid 4-6%, Nitric acid 0-1%, Hydrofluoric acid 0-1%, Acetic 0-0.1%, Water 92-100%		K. Handling Codes for Wastes Listed Above a. b. c. d.					
15. Special Handling Instructions and Additional Information Emergency Response Telephone Number (800) 424-9300 (chemtree) DOT ERG #60 Ia. Additional EPA waste code D007. EH Permit # 4-93052513							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month Day Year 12/1/93			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name James Axel		Signature James Axel		Month Day Year 12/1/93			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year			
19. Discrepancy Indication Space							
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name		Signature		Month Day Year			

DO NOT WRITE BELOW THIS LINE.

92301672

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA, CALL 1-800-852-7575

**UNIFORM HAZARDOUS
WASTE MANIFEST**

1. Generator's US EPA ID No.

Manifest Document No.

2. Page 1

Information in the shaded areas
is not required by Federal law.

CA D0816511001050116712

of 1

3. Generator's Name and Mailing Address

Douglas Aircraft Company Attn: R. Tuell
19503 S. Normandie Avenue Malibu: CA 90599

4. Generator's Phone

(213) 90502

5. Transporter 1 Company Name

6. US EPA ID Number

Landlaw Environmental Service of CA, Inc.

8. US EPA ID Number

9. Designated Facility Name and Site Address

10. US EPA ID Number

Norris Environmental Services
5210 S. Boyle Avenue
Los Angeles, CA 90058

CA D097030993

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers
No. Type

13. Total
Quantity

14. Unit
Wt/Vol

15. Waste Number

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

A. State Manifest Document Number

92301672

B. State Generator's ID

C. State Transporter's ID

D. Transporter's Phone

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

I. Waste Number

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

State

EPA/Other

Printed/Typed Name

Signature

Month

Day

Year

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month

Day

Year

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month

Day

Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month

Day

Year

DO NOT WRITE BELOW THIS LINE.

WHEN COMPLETING THIS FORM REFER TO 40 CFR, PART 262, APPENDIX AND CCR, TITLE 22, DIVISION 4.5, CHAPTER 12, APPENDIX

INSTRUCTIONS FOR GENERATORS

Item 1. Generator's U.S. EPA ID Number—Manifest Document Number: Enter the generator's U.S. EPA 12-digit identification number. The five-digit space to the right can be used for your own internal tracking system. A number there is not required.

Item 2. Page 1 of _____: Enter the total number of pages used to complete the Manifest plus the number of Continuation Sheets, if any.

Item 3. Generator's Name and Mailing Address: Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number: Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name: Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number: Enter the U.S. EPA 12-digit identification number of the first transporter identified in Item 5.

Item 7. Transporter 2 Company Name: If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number: If applicable, enter the U.S. EPA 12-digit identification number of the second transporter identified in Item 7.

Item 9. Designated Facility Name and Site Address: Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address which may differ from the company mailing address.

Item 10. U.S. EPA ID Number: Enter the U.S. EPA 12-digit identification number of the designated facility identified in Item 9.

Item 11. U.S. DOT Description: Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177. For non-RCRA hazardous wastes, describe per instructions in the Appendix to Chapter 12, Title 22, California Code of Regulations, Division 4.5.

Item 12. Containers (No. and Type): Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I—Types of Containers

DM = Metal drums, barrels, kegs	TP = Tanks, portable
DW = Wooden drums, barrels, kegs	TT = Cargo tanks (tank trucks)
DF = Fiberboard or plastic drums, barrels, kegs	TC = Tank cars
CW = Wooden boxes, cartons, cases	DT = Dump truck
CF = Fiber or plastic boxes, cartons, cases	CY = Cylinders
BA = Burlap, cloth, paper, or plastic bags	CM = Metal boxes, cartons, cases (including roll-offs)

Item 13. Total Quantity: Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.): Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II—Units of Measure

G = Gallons (liquids only)	Y = Cubic yards	M = Metric tons (1,000 kg)
P = Pounds	L = Liters (liquids only)	
T = Tons (2,000 lbs.)	K = Kilograms	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information: Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, generators must enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification: The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

INSTRUCTIONS FOR TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials: Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials: Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note—International Shipments—Transporter Responsibilities: Exports—Transporters must sign and enter the date the waste left the U.S. in Item 15, and for RCRA hazardous waste exports, must ensure the waste is accompanied by an EPA Acknowledgement of Consent. Imports: RCRA hazardous waste shipments which are transported into the U.S. from a foreign country must be accompanied by a Manifest; non-RCRA hazardous waste shipments transported from a foreign country into or through California must also be accompanied by a Manifest. Transporters who transport any hazardous waste into the U.S. from abroad must assume generator responsibilities for completion of the Manifest [40 CFR 263.10(c)(1)].

INSTRUCTIONS FOR OWNERS OR OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space: Refer to California Title 22, Section 66264.72 and 66265.12; 40 CFR 264.72 and 265.72 for help in completing this part. In this space you must note any significant discrepancy between the waste described on the Manifest and the waste you actually received. If you cannot resolve significant discrepancy within 15 days of receiving the waste, you must submit a letter to your DTSC Regional Administrator describing the discrepancy and your attempts to reconcile it. A copy of the Manifest at issue must be enclosed with the letter.

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19. Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

CALIFORNIA REQUIRED ITEMS

Generators to Enter:

- If you will be paying the disposal taxes due under Section 25174 of the Health and Safety Code directly to the Board of Equalization (Board), enter your Hazardous Waste Fee Account number issued by the Board for paying the taxes due under this section. This account number is a 12-character number beginning with HA or HY. Other Board numbers you may hold are not valid for this purpose. Any person willfully falsifying or misusing their account number to evade or defeat the payment of the taxes is guilty of a felony. If you do not have an account number and are subject to these taxes, you should contact the Board at (916) 322-9477, Monday through Friday, between 8 a.m. and 4 p.m.
- Enter the certificate of compliance number of the first vehicle used to transport the hazardous waste.
- If applicable, enter the certificate of compliance number of the vehicle used by Transporter 2, to transport the hazardous waste.
- Enter the California waste category number. Select appropriate number from Table III. Review entire table before selecting a number. For RCRA waste(s), enter the EPA's hazardous waste code from 40 CFR 261.30-33. To obtain federal assistance, call 800-424-9346 between 8:30 a.m. and 4:30 p.m. Eastern time.
- Enter chemical composition for each waste category. List components corresponding to the category entered.

TSDF Operator to Enter

- Enter EPA ID number.
- Enter waste handling code(s). Select appropriate code(s) from Table IV.

California Restricted Waste

711. Liquids with cyanides $\geq 1,000$ Mg./L	725. Liquids with mercury ≥ 20 Mg./L
721. Liquids with arsenic ≥ 500 Mg./L	726. Liquids with nickel ≥ 134 Mg./L
722. Liquids with cadmium ≥ 100 Mg./L	727. Liquids with selenium ≥ 100 Mg./L
723. Liquids with chromium (VI) ≥ 500 Mg./L	728. Liquids with thallium ≥ 130 Mg./L
724. Liquids with lead ≥ 500 Mg./L	731. Liquids with polychlorinated biphenyls ≥ 50 Mg./L

Table III

741. Liquids with halogenated organic compounds $\geq 1,000$ Mg./L
751. Solids or sludges with halogenated organic compounds $\geq 1,000$ Mg./Kg.
791. Liquids with pH ≤ 2
792. Liquids with pH ≤ 2 with metals.
801. Waste potentially containing Dioxins.

California Nonrestricted wastes

Inorganics	Organics	Sludges
121. Alkaline solution (pH ≥ 12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)	211. Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)	411. Alum and gypsum sludge
122. Alkaline solution without metals pH ≥ 12.5	212. Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)	421. Lime sludge
123. Unspecified alkaline solution.	213. Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)	431. Phosphate sludge
131. Aqueous solution ($2 < \text{pH} < 12.5$) containing reactive anions (azide, bromate, chlorate, cyanide, fluoride, hypochlorite, nitrite, perchlorate, and sulfide anions)	214. Unspecified solvent mixture	441. Sulfur sludge
132. Aqueous solution with metals ($<$ restricted levels and see 121)	221. Waste oil and mixed oil	451. Degreasing sludge
133. Aqueous solution with total organic residues 10 percent or more	222. Oil/water separation sludge	461. Paint sludge
34. Aqueous solution with total organic residues less than 10 percent	223. Unspecified oil-containing waste	471. Paper sludge/pulp
35. Unspecified aqueous solution	231. Pesticide rinse water	481. Tetraethyl lead sludge
141. Off-specification, aged, or surplus inorganics	232. Pesticides and other waste associated with pesticide production	491. Unspecified sludge waste
151. Asbestos-containing waste	241. Tank bottom waste	
161. Fluid Catalytic Cracker waste	251. Still bottoms with halogenated organics	
162. Other spent catalyst	252. Other still bottom waste	
171. Metal sludge (see 121)	261. Polychlorinated biphenyls and material containing PCBs	
172. Metal dust (see 121) and machining waste	271. Organic monomer waste (includes unreacted resins)	
181. Other inorganic solid waste	272. Polymeric resin waste	
	281. Adhesives	
	291. Latex waste	
	311. Pharmaceutical waste	
	321. Sewage sludge	
	322. Biological waste other than sewage sludge.	
	331. Off-specification, aged, or surplus organics	
	341. Organic liquids (nonsolvents) with halogens	
	342. Organic liquids with metals (see 121)	
	343. Unspecified organic liquid mixture	
	351. Organic solids with halogens	
	352. Other organic solids	

Miscellaneous

- Empty pesticide containers 30 gallons or more
- Other empty containers 30 gallons or more
- Empty containers less than 30 gallons
- Drilling mud
- Chemical toilet waste
- Photochemicals/photoprocessing waste
- Laboratory waste chemicals
- Detergent and soap
- Fly ash, bottom ash, and retort ash
- Gas scrubber waste
- Baghouse waste
- Contaminated soil from site clean-ups
- Household wastes
- Auto shredder waste

Table IV

01 Recycle	03 Landfill	06 Surface Impoundment	14 Transfer Station	16 Treatment Pond (excludes evaporation)
02 Injection Well	04 Land Application	07 Thermal Treatment (includes incineration)	15 Tank Treatment	99 Other

92301612
IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7557

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address Douglas Aircraft Company 19503 S. Normandie Avenue Torrance, CA 90502 Generator's Phone (310) 533-7926 or (310) 533-7231		CAID081651100015	011672		A. State Manifest Document Number 92301672
5. Transporter 1 Company Name Laidlaw Environmental Services of CA, Inc.		CAID000083121			B. State Generator's ID HAHQ360056981
7. Transporter 2 Company Name Disposal Control Service		CAID080034184			C. State Transporter's ID 444448A
9. Designated Facility Name and Site Address Norris Environmental Services 5215 S. Boyle Avenue Los Angeles, CA 90058		CAID097030993			D. Transporter's Phone (310) 518-4700
					E. State Transporter's ID 412148
					F. Transporter's Phone 909 983-0342
					G. State Facility's ID
					H. Facility's Phone (213) 588-7111
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number State EPA/Other
a. RQ, Waste Corrosive Liquids, N.O.S. (Chromic acid, Nitric Acid), 8, UN1760, PG II, (D002, D007)		001 TT	07580	P	State 792 EPA/Other D002
b.					State EPA/Other
c.					State EPA/Other
d.					State EPA/Other
J. Additional Descriptions for Materials Listed Above QID# E0106200002 CR: Chromic Acid Anodizing Solution From Baker Tank And With Rinse water from Tank #5 Titanium Pickle Tanks Chromic acid 4-6%, Nitric acid 0-1%, Hydrofluoric acid 0-1%, Active 0-0.1%, Water 92-100%		K. Handling Codes for Wastes Listed Above a. b. c. d.			
15. Special Handling Instructions and Additional Information Emergency Response Telephone Number (800) 424-9300 (Chemtrec) DOT ERG #60 Ia. Additional EPA Waste Code D007. EH Permit # 4-93052513					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month Day Year 12/1/93	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name James Axel		Signature James Axel		Month Day Year 12/1/93	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Signature Month Day Year					

DO NOT WRITE BELOW THIS LINE.

See instructions on back of page 6.

Department of Toxic Substances Control
Sacramento, California

92301612

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA, CALL 1-800-852-7575

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address Douglas Aircraft Company 19503 S. Normandie Avenue Torrance, CA 90502		CAID0865110001501672	Attn: R. Tuell Mail Code: C6-59	A. State Manifest Document Number 92301672	
4. Generator's Phone (310) 533-7926 or (310) 533-7231		6. US EPA ID Number CAID000083121	B. State Generator's ID HAIHQ36005698		
5. Transporter 1 Company Name Laidlaw Environmental Services of CA, Inc.		8. US EPA ID Number CAT080034184	C. State Transporter's ID 4112148A		
7. Transporter 2 Company Name Disposal Control Service		10. US EPA ID Number CAT080034184	D. Transporter's Phone (310) 518-4700		
9. Designated Facility Name and Site Address Norris Environmental Services 5215 S. Boyle Avenue Los Angeles, CA 90058		12. Containers No. Type 001 TT 07580	13. Total Quantity 07580	14. Unit P	E. State Transporter's ID 412148
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) a. RQ, Waste Corrosive Liquids, N.O.S. (Chromic acid, Nitric Acid), 8, UN1760, PG II, (D002, D007)		F. Transporter's Phone 909-983-0342			
		G. State Facility's ID			
		H. Facility's Phone (213) 588-7111			
J. Additional Descriptions for Materials Listed Above QID# E0106200002 CR: Chromic Acid Anodizing Solution From Baker Tank Area with Rinse water from Tank 75 Titanium Pickle Tanks Chromic acid 4-6%, Nitric acid 0-1%, Hydrofluoric acid 0-1%, Active 0-0.1%, Water 92-100%		K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Emergency Response Telephone Number (800) 424-9300 (Chemtrec) DOT ERG #60 Ia. Additional EPA Waste Code D007. EH Permit # 4-93052513					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of the consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable federal, state and international laws.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month Day Year 12/1/93	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name James Axel		Signature James Axel		Month Day Year 12/1/93	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name		Signature		Month Day Year	

DO NOT WRITE BELOW THIS LINE.

LAND DISPOSAL RESTRICTION NOTIFICATION

Generator Name: Douglas Aircraft Company EPA ID Number: CAD086510005Manifest Number: 01672/92301672 Date of Shipment: 12-10-93Indicate Waste Line Item (11): a

This notification is hereby submitted to **NORRIS ENVIRONMENTAL SERVICES** in compliance with EPA regulations described in 40 CFR Part 268 which prohibit the land disposal of certain hazardous wastes, unless these wastes are treated to meet specified standards or treated using specified treatment technologies.

I have marked the appropriate box(es) below, which indicates how my waste must be managed to conform to land disposal ban and/or federal regulations.

RCRA Land Disposal NotificationCalifornia List Wastes Notification

- ☐ Liquid hazardous waste including free liquids associated with any solid or sludge containing free cyanide at concentrations greater than or equal to 1000mg/L.

Treatment Standard-Cyanide Destruction Stabilization

- ☒ Liquid hazardous wastes, including free liquids associated with any solid or sludge, containing the following metals (or elements) at concentrations greater than or equal to those specified below:

Treatment Standard-Metals Recovery Stabilization

(check those that apply)

- | | |
|---|-------------|
| <input type="checkbox"/> Arsenic and/or compounds (as As) | 5.0 mg/L; |
| <input type="checkbox"/> Barium and/or compounds (as Ba) | 100.0 mg/L; |
| <input type="checkbox"/> Cadmium and/or compounds (as Cd) | 1.0 mg/L; |
| <input checked="" type="checkbox"/> Chromium (VI and/or compounds as Cr VI) | 5.0 mg/L; |
| <input type="checkbox"/> Lead and/or compounds (as Pb) | 5.0 mg/L; |
| <input type="checkbox"/> Mercury and/or compounds (as Hg) | 0.2 mg/L; |
| <input type="checkbox"/> Selenium and/or compounds (as Se) | 1.0 mg/L; |
| <input type="checkbox"/> Silver and/or compounds (as Ag) | 5.0 mg/L; |

- ☐ Liquid hazardous wastes that are primarily water and contain halogenated organic compounds (HOCs) in total concentration greater than or equal to 1,000 mg/L and less than 10,000 mg/L. HOCs (see attached listing of HOC constituents)

Treatment Standard-Carbon Absorption Steam Stripping

- ☐ Liquid hazardous wastes containing polychlorinated biphenyls (PCBs) at concentrations greater than or equal to 50 ppm.

Treatment Standard-Incineration, high efficiency boiler, other thermal treatment

- ☒ Liquid hazardous wastes having a pH less than or equal to two(2) or pH equal to or greater than 12.5.

Treatment Standard-Neutralization Stabilization

- ☐ The spent solvent wastes specified in 40 CFR 261.31 as EPA Hazardous Wastes Nos F001, F002, F003, F004 and F005.

Treatment Standard-Specify technology used to meet Table CCWE. Check constituent(s) on Table CCWE which were reduced below treatment standards

The most recent copy of waste analysis or a description of the knowledge upon which this notification is based is attached. I hereby certify that all information submitted in this and all associated documents is complete and accurate to the best of my knowledge and information.

Print Name Robert G. Tuell, Jr.Signature Robert G. Tuell, Jr.Title Senior Plant EngineerTelephone Number (310) 533-7926Date 12-10-93Waste Subject to Variance

- ☐ The waste identified above is subject to a case-by-case extension under 40 CFR 268.5, a no-migration petition under 40 CFR 268.6, a nationwide variance under Subpart C, or is soil or debris generated from a response action taken under CERCLA or corrective action under RCRA.

Waste Requires Treatment

- ☒ I am the initial generator of an untreated waste identified above which must be treated in the appropriate treatment standard set forth in 40 CFR 268 Subpart D, or where no treatment standard exists for the California List Waste, the waste must be treated to the levels specified under 40 CFR 268.32.

Waste Treated to Performance Standards

- ☐ The waste identified above has been treated in compliance with the applicable performance standards specified in 40 CFR 268 Subpart D and/or the applicable prohibitions set forth in 40 CFR 268.32. "I certify under penalty of law that I have personally examined and am familiar with the treatment technology and operation of the treatment process used to support this certification and that, based upon my inquiry of those individuals immediately responsible for obtaining this information, I believe that the treatment process used to support this certification and that, based upon my inquiry of those individuals immediately responsible for obtaining this information, I believe that the treatment process has been operated and maintained properly so as to comply with the performance levels specified in 40 CFR Part 268 Subpart D and all applicable prohibitions set forth in 40 CFR 268.32 or RCRA Section 3004(s) without dilutions of the prohibited waste. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

WEIGHT TICKET

VENDOR: Disposal Central

GROSS 44,960 P

TRUCK #: 1519/2447

TARE 37,380 P

DATE: 12-10-93

NET 7,580 P

CONTENTS: Acids from tanks #195 (hydrochloric) 95 + misc.

DISPOSAL FACILITY: NORRIS

DRUM COUNT: 1

DRIVER: James Noel

GALLONS: 1

STATE MANIFEST DOCUMENT NUMBER: 01672/92301672